

# FORD AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD Changer port of your factory (OEM) Radio into an auxiliary input. Auxiliary devices such as XM Radio, iPods, Video systems, MP3 Players can be added to the factory (OEM) radio without using an FM Modulator, resulting in optimum sound quality.

Model	Year	Part #	Location	Notes
Crown Victoria	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 - Premium Audio System
Crown Victoria	1995-1997	FRDR-AUX	RCU in trunk	Radio Series 852 - JBL or LUX Audio System
Crown Victoria	1998-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 870 - Use <b>FRDW-AUX</b> if pre-wired
Crown Victoria	2003-2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Use FRDW-AUX if pre-wired
Escape	2001-2003	RDN-AUX	20-Pin connector at headunit	Radio Series 868
Escape	2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Radio Model 3L8T-18C815-FB
Econoline	1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Econoline	1998-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 868, 870 or 815
Escort	1997-2003	FRDW-AUX	12-Pin data cable in trunk/rear	Radio Series 858 (Oval)—Use <b>FRDF-AUX</b> at H/U if not pre-wired
Excursion	2000-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Expedition	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Expedition	1999-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 870
Explorer	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 - Premium Audio System
Explorer	1995-1997	FRDR-AUX	RCU rear passenger side panel	Radio Series 852 - JBL or LUX Audio System
Explorer	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
F-150 Pick Up	1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165- Not compatible with the new 2004 F-150
F-Series Pick Up	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Freestar	2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Radio Models 3F2T-18C868-AJ and 3F2T-18C869-AJ
Focus	2000-2003	FRDC-AUX	12-Pin connector at headunit	Radio Series 815 or 876—Not compatible w/ Blaupunkt H/U.
HN80 Heavy Duty	1996-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Mustang	2001-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 815 & 868
Ranger	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Ranger	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Sport Trac	2000-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 815
Taurus	1996-2004	FRDR-AUX	RCU in Trunk or Rear	Radio Series 858 (Oval/Trapezoidal)
Thunderbird	2002-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 132 or 868
Windstar	1999-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 815

NOTE: Not compatible with 2003-up models equipped with 6-disc in-dash headunit.